

SWAN, HUNTER, & WIGHAM RICHARDSON, LIMITED.

Ship, Engine, Boiler & Floating Dock Builders & Repairers,

WALLSEND-ON-TYNE.

London office, 21, Russell Square, W.C.1.



References Ours 6A.LC.  
Yours

3rd April, 1939.  
Monday.

The Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street,  
LONDON E.C.3.



All offers are subject to our usual strike, accident and guarantee clauses and to the other conditions in our printed form of contract.

Telephone: WALLSEND 63121.

Telegraphic address: SWANHUNTER, WALLSEND.

Dear Sir,

NO. 1567 SHIP - PUMPING ARRANGEMENT.

With reference to the pumping arrangement plan returned with your letter dated the 8th December, we wish to advise you that the size of the centre suction and air pipes to No.2 tank, port and starboard, have been increased from 3" to 4" diameter.

Yours faithfully,

FOR

SWAN, HUNTER WIGHAM RICHARDSON, LTD.

*I. M. Bocher*

NAVAL ARCHITECT



©2019

Lloyd's Register  
Foundation

W174-0079.1

Using the Lloyd's Register of Shipping  
Information on the Lloyd's Register of Shipping

Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.

4 APR 1939

*Noted, Advise Newcastle Surveyors*  
*R.M.*  
*4-4-39*

Dear Sir,  
With reference to the bombing arrangements being  
made for the ship, I have been instructed from the  
Director of the Admiralty to advise you that the  
arrangements for the ship are being made on the  
basis of the information received from the  
Director of the Admiralty on the 2nd of April.

NO. 1282 SHIP - BOMBING ARRANGEMENTS.



© 2019 Lloyd's Register Foundation

RECEIVED  
APR 4 1939  
LLOYD'S REGISTER



WATTS & FLETCHER

Ship Engineering, Surveying & Consulting Engineers & Surveyors

WATTS & FLETCHER & MICHAEL RICHARDSON LIMITED

15, Abchurch Lane,  
London, E.C. 4.

11 PROS 4 F1 W