

SWAN, HUNTER, & WIGHAM RICHARDSON, LIMITED.

Ship, Engine, Boiler & Floating Dock Builders & Repairers,

WALLSEND-ON-TYNE.

London office, 21, Russell Square, W.C.1.



References Ours 6W.LC.
Yours

24th October, 1938.
Monday.

The Secretary,
Lloyd's Register of Shipping,
71 Fenchurch Street,
LONDON E.C.3.



3 plans

Dear Sir,

NO. 1567 SHIP.

It has been suggested to make the tank side connections in above ship of welded construction, as shown on the enclosed sketch (in triplicate).

We shall be glad if you will examine this proposal and, if possible, let us have your approval by telephone on Tuesday as it is very necessary that our material be ordered without delay.



Yours faithfully,

SWAN, HUNTER, WIGHAM RICHARDSON, LTD.

I.R. Bocken

NAVAL ARCHITECT.

ENCLOSURES.



© 2019

Lloyd's Register
Foundation

W174-0285

Telephone: WALLSEND 63121.

Telegraphic address: SWANHUNTER, WALLSEND.

All offers are subject to our usual strike, accident and guarantee clauses and to the other conditions in our printed form of contract.

Referred to the Chief Ship Surveyor.

25 OCT 1938

URGENT

S.H.W.R. 1567

Welded construction
of tank side connections

Ltr. 24.10. Ansd. 25.10.
2 plans 1 retained
P.C. Nwc.

NO. 1287 SHIP.

LONDON
25 OCT 1938
REGISTER

LONDON E.C.2.
AT LONDON E.C.2.
The Secretary,
Lloyd's Register of Shipping.

LONDON
25 OCT 1938

Reference
Once CA. 10.

WITTENBERG & LANE

SHIP BUILDERS, 10, FLEET STREET, LONDON E.C.4.

SWAN HUNTER & WILKINSON, LONDON E.C.4.