

Gls
COPY.

C1337

Harpasa
GLASGOW REPORT No 54172



NEWCASTLE ON TYNE.

16th November 1933.

Messrs. North Eastern Marine Engineering Co. Ltd.,

25th & 28th Sept. 1933

8

S.R.452,

- - and Elements

Messrs. D. Rowan & Co. Ltd.,

their No. 961.

XXXX

GLASGOW REPORT No 54172

660

220

10% of the Elements were subjected, in the presence of the
Undersigned, to 1500 lbs. per square inch water pressure and found
Two pairs tested - satisfactory.

S.R.452.

660

220

W.B.25-9-33.

See also attached sheet.
(S.S.H.)

In W.B.
Hob
NEWCASTLE ON TYNE.

© 2020

Lloyd's Register

W175-0108(112)

W175-0108(112)

COPY.

- 2 -

1E

Superheater Headers - S.H. 482.

15th November 1933.

Two pairs tested :-
of Engine

NO. S.H. 482.
LLOYD'S TEST
660 lbs.
W.P. 220 lbs.
W.B. 28-9-33.

Fee :- £2.13.4

If Boilers fitted with forced draft

Tail Shaft. If fitted with a continuous

If fitted with an outside gland or

approved type

J. W.B.
W.B.

SURVEYOR TO LLOYD'S REGISTER.

NEWCASTLE ON TYNE.

Harpasa
GLASGOW REPORT No. 54172

*2 SB } 220 lbs.
1 Qua SB }*

*The surveyor should be requested to
inspect the boiler house from the
outside steam turbine*



© 2020 175-01K

Lloyd's Register

175-0108(212)