

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

24 JUN 1937

VESSEL'S NAME

"HANNE"

Rpt.

Vienna

No. 1474

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

Braila

The Vienna Surveyor, who was authorised, reports the vessel examined afloat. The greater part of the requirements of the 3rd S.S.No.2, due 1,37, have been complied with, five shell plates faired, a deck plate doubled and minor repairs effected.

The wood deck requires to be repaired and caulked and the chain locker requires to be further examined when the chain cables are ranged.

The cross bunker is being converted into an oil fuel bunker in accordance with approved plans and on completion this will require to be tested.

For the purpose of carrying cattle a temporary deck has been fitted in No.2 hold.

It is submitted action be deferred and enquiry made as to what arrangements are proposed for the completion of the Special Survey.

Insert in S.R.L. 'Repairs to wood deck'

23.6.37

The Surveyor should be requested in future similar cases to conclude his report with a statement of the items & repairs which remain to be dealt with to complete the Special Survey.

© 2019  
Lloyd's Register  
Foundation

W178-0005