

Lloyd's Register of Shipping,

T.S. 9
assigned) as

2nd 12.42.

1

18 JUN 1943

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "INCOMATI" REPORT Liv No. 119524

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Dkg. & Gen. Exam. for post. of 1st. S.S. No. 2 due 4.42.
When due
"EXAMINED 5.43" - 12 MONTHS

Subject to permanent repairs to two holes
in keel plating in way of No. 1 tank at the first
opportunity.

5.43 Liv.
"Examined 5.43"

SJR 18.6.43



© 2019

Lloyd's Register
Foundation

W179-0135

is desired as to whether the requirements of Circular 1748
were attended to and what arrangements were made for the