

Messrs. Bremer Vulkan's Nos. 748/9/50

It is submitted Mr. Johnson be informed that the strengthening to the quadrant arranged by him in the case of No. 748 has been duly noted.

It is suggested that in the case of Nos. 749/50 if practicable it would be well if the doubling plates were extended farther along the arms and tapered off.

It is noted that the Designers and makers are proposing to carry out comparative tests on this type of quadrant and the normal cast steel quadrant and the results of these tests will be awaited with interest.

J.R.

19.3.38.

W.J.



© 2019

Lloyd's Register
Foundation

W180-00 61