

19 JUN 1942

Received from Chief Surveyors.....  
 to Chief Surveyors.....

SHIP'S NAME J. A. MOFFETT JR. REPORT Gal. No. 4263

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — (Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING. ~~When due~~

Action has been deferred for equipment.

45 fathoms of missing and 135 fathoms of worn chain  
 cable require to be replaced at the first opportunity.



© 2019

Lloyd's Register  
 Foundation

was  
 3-6-42

W 181-0127