

COPY.

Lloyd's Register of Shipping.



Port

Galveston, Texas.

June 13, 1942.

This is to Certify *that I have*

Surveyed the Steel Twin Screw S/S "JACOBUS STEIN", 10000 tons

gross of Netton, afloat and on dry docks at Todd Galveston Dry

Docks, Inc. on the 14th May, 1942 and subsequent dates for docking,
repairs and general condition survey prior to being taken over by
the U.S.N.M.,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and

that I have Recommended that she be continued as classed,

viz: #10001, with fresh record of survey 5.42 (May, 1942) and
notation "Docking Date - 5.42", subject (as previously recommended)
to indented top side shell plating etc., starboard side amidships
in way of fuel oil bunker (collision damage) being permanently
repaired at a convenient opportunity,

being fit to carry Dry and Perishable Cargoes.

Now done: Bottom (recoated) and both rudders removed, overhauled
stocks machined, all bushings renewed etc. & refitted in good condi-
tion.

Lower Anchors and chain cables (ranged), chain locker (recoated)
and examined.

Also generally examined all cargo spaces, tween decks, deck erection
spaces, decks, hatch-
ways, hatches, beams,
battening arrangements,
ventilators and coamings,
etc., and after peak tank
internally. All found in good condition.

Erni Rennie
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."