

COPY.

Lloyd's Register of Shipping.



Port Galveston, Texas.

June 18, 1942.

This is to Certify that I have

Donkey Part and both Screw Shafts, etc.
Surveyed the Boilers and Machinery of the Steel Twin Screw S/V "JAGERS-MONTZIR", 10083 tons gross of Batavia, afloat and on dry dock at Todd Cal. S.S. Inc. on the 14th May, 42 & subsequent dates for Dock., exam. of both Screw Shafts, bushings, propellers, Sea connections, part continuous oil engine survey and machy. repairs, and complete Donkey Boiler Survey (due 4,42)

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of DBS-6,42 now (Donkey Boilers surveyed June, 1942), Screw Shaft 06, Port and Starboard, seen 5,42, and +LMC, CS (with date)

be made in the Register Book in the case of this vessel when the survey has been completed.

Parts now examined:—

Propellers, all sea connections and fastenings (also both screw shafts, the starboard shaft machined and bushings renewed).

Main engine:—Port Nos. 1,4, Starb. Nos. 3,4, cylinder, liner, pistons, rod, valves, gears, covers.

Above piston rods also of two (2) spares machined true. New upper piston installed on spare piston assembly and remaining piston crown built up by welding.

Starb. forward auxiliary oil engine:—No. 5 cylinder, piston, connecting rod, top and bottom ends and crank pin - new cylinder liner fitted. All found or now placed in order.

Also donkey boilers surveyed.

Wm Rennie

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are duly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any instances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."