

Do. of Forecastle 14.10
Do. of Houses on Dk. Round 116.39
Do. of excess of Hatchways 50.56

Length on deck from fore part of stem to after part of stern post 400

By whom built Work

copy King Edward

Rpt. 36.

For the information of Surveyors and the Committee only.

Received at Office 19

Lloyd's Register of Shipping.

(Report on Vessel No. Port Belfast)

No. SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by Messrs Sunderland Forge & Eng Co. Ltd of Sunderland, for the Vessel No. 444, being built by Hockman, Clark & Coy Ltd of Belfast been inspected by me as set forth below and found to be, so far as can be seen, Sound

ings or Castings.

1961

D. D. Williamson

Sunderland, 11-9-19

	STERN FRAME.	RUDDER FRAME.	STEM.
...	/	Scrap Iron	/
...		Forged	
...		10" dia to 1 1/2" dia	
...		Finished	
Inspection ...		9-9-19 to 10-9-19	
Inspected }			
CASTINGS.			
Standard Test			
Pieces.			
Test—			
square inch			
per cent. ...			
ling Test—			
Angle before fracture			
Drop Test—			
Height from ground ...			
Hammering Test—			
If made according to Rules			
and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Original posted to Belfast 12.9.19


Not means
Insd.

Fee (if any chargeable) £

To be paid at

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

17m. 3.19 T.



© 2019

Lloyd's Register Foundation

W184-0107

Plate, Tee Bulb, or Channel.....	0	0	40	0	5	40	Deck, material and thickness	Steel
Angles on upper edge.....								