

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

16th September, 1937.

Yard No. 1555

Dear Sirs,

M.

With reference to the telephone conversation with your Mr. Inman yesterday, I have to inform you that as the Rule depth of longitudinal is 14 inches the number of rivets in the lugs attaching the bottom longitudinals to the transverses may be six instead of eight as shown on the plan of midship section.

I am, Dear Sirs,

Yours faithfully,

Secretary.

Messrs. Swan, Hunter & Wigham
Richardson, Ltd.,
WALLSEND/TYNE.



© 2020

Lloyd's Register
Foundation

W186-0328