

## Lloyd's Register of Shipping.

(Report on Machinery, No. 31581)Port SunderlandNo.        ENGINE ~~FORGINGS~~ OR CASTINGS.

I have to report that the ~~Forgings or Castings~~, as herein described, manufactured by Mr E Jephling & son of Sunderland for the Engines No. 271-2 being repaired constructed by Mr J Dickinson & son of Sunderland for the Ship No.       , being built by

of        have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to

Mr J Dickinson & son of Sunderland

Mark on ~~Forgings or Castings~~.

Lloyd's

No. 827717.12.34

1 M.S. Valve

J Dale

Sunderland


18.12.34

	CRANK SHAFT.	<del>THRUST</del> SHAFT.	INTERMEDIATE SHAFT.	TUBE SHAFT.
	FLYWHEEL SHAFT.			SCREW SHAFT.
Material* ...		Cast Steel		
How made ...		Electric furnace		
If Annealed ...		yes		
Dimensions, Forgings		Pattern		
Weight, Castings		cons. on the		
Progress on { Inspection }		7-0.0		
Tests on Standard Test Pieces.		belonging & testing		
Tensile Test— Tons per square inch		30.0		
Extension per cent		32.1		
Cold Bending Test— Angle before fracture		120		
Dates when Inspected		14-17/12/34		

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

Fee (if any chargeable) £ Monthly 7/- To be paid at

\* If of wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.



© 2020

Lloyd's Register  
Foundation

W189-0185