

14 AUG 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "MACDHUI" ..... REPORT Syd. No. 18834

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented keel plate No.2 and shell plates A.3 and D.4 (p.s) and A.3 & 4 (s.s) all from aft, being dealt with at the Owners' convenience.

The SYDNEY N.S.W. Surveyors report (5,42) the vessel placed in dry dock, bottom coated, decks hatchways, ventilators etc. examined and found in good condition.

The indented plating, as above, continues efficient.

It is submitted the vessel appears worthy to remain as classed with record of docking survey 5,42 subject as above.

LOCAL  
with freeboard } Subject etc.  
5,42 Syd. }

6/11/42  
10-8



© 2019

Lloyd's Register  
Foundation

W192-0289