



# Lloyd's Register of Shipping,

95, Bothwell Street, Glasgow, c.2.

15th February, 1932.

LLOYD'S REGISTER  
RECEIVED  
16 FEB 1932

Reference

Sir,

With reference to my letter of the 11th instant in regard to the yard number of the steamer "MARGOT", I beg to acquaint you that it now appears that the number 779, which was that given on the Electric Lighting Report, was not correct and the yard number should have been given thereon as 784.

I shall be obliged if you will kindly have the record on the Electric Lighting Report amended as well as the record in the Appendix to the Register Book.

I am, Sir,

Your obedient servant,

*P. H. Warlow*

Local Secretary.

The Secretary,  
LONDON.



© 2019

Lloyd's Register  
Foundation  
70926

W194-0161

Referred to the Chief Engineer Surveyor

16 FEB 1972

Referred to Mr Bishop

*handed*

*adm.*

TO: MR BISHOP  
FROM: MR BISHOP

YOUR REFERENCE TO THE

IS NOT

THE RECORD TO THE OFFICE TO THE SURVEYOR

RECORD ON THE RECORDS OF THE SURVEYOR

Y EARLY BE ADVISED TO THE SURVEYOR

ON THE

COLLECT THE RECORDS FROM THE SURVEYOR

WHICH ARE THE RECORDS OF THE SURVEYOR

AND TO ADVISE THE SURVEYOR TO THE SURVEYOR

TO ADVISE THE SURVEYOR TO THE SURVEYOR

YOUR REFERENCE TO THE RECORDS OF THE SURVEYOR

ON THE

YOUR REFERENCE TO THE



© 2019  
Lloyd's Register  
Foundation