


HAMILTON'S YARD NO. 446

Mr. Slowman assistant to Mr. Brough at Admiralty rang up to say that our local surveyor in Glasgow was asking for reverse current trips in some battery circuits. The batteries are for special service, he could not tell me over the 'phone what these services were.

The local Admiralty Overseer in Glasgow had telephoned Mr. Slowman of the position.

Mr. Slowman asked if further consideration could be given and the Glasgow Surveyors informed by telephone as soon as possible that reverse current trips were not required in the circuits of these batteries for special purposes in the case of the above vessel.



8-8.
© 2019
10.4.41.

Lloyd's Register
Foundation

W 195-0 227