

20 JUL 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME ..... PAMPAS ..... REPORT ..... Alx. .... No. 2316 .....

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

For conditions of class see Endorsement 16.12.41.

The ALEXANDRIA Surveyor reports (3.42) the vessel examined afloat and defective E.W. repairs to sternframe arch re-welded.

The Surveyor recommends the upper part of sternframe be specially examined by 9.42.

Some repairs have been effected to a cargo derrick.

It is submitted the vessel appears worthy to remain as classed without fresh record of survey subject as now recommended and as above.

As now, subject etc.

AMEND S.R.L.:- Regarding sternframe "re-welded 3.42."

CSM  
20.7.42.



© 2019

Lloyd's Register Foundation

W206-0102