

COPY.

Lloyd's Register of Shipping.



Port ALEXANDRIA

10th. March, 1942.

This is to Certify *that I have*

Surveyed the X.V. "PAMPAS" 5400 tons gross of London afloat,
on account of defective electro welding of upper part of stern
frame.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have **Recommended** *that she be* continued as classed
+ 100 A.I. with freeboard subject to further examination of
the upper part of stern frame September 1942.

being fit to carry dry and perishable cargo.

M. B. B. B.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."