

T.M.V. "Persephone".

Hamb 16396.

It is submitted the Hamburg Surveyors be requested to state the area of the safety valves of the two exhaust gas boilers omitted from their report.

W.D.

18/6/25.

19/6/25.

W 207-0087

I have transmitted to the Committee of Lloyd's