



# Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 18th March, 1938.

LLOYD'S REGISTER  
19 MAR 1938  
LONDON

Dear Sir,

In reply to your letter of the 17th instant regarding the diameter of the thrust shafts made for Messrs. Richardsons Westgarth & Co., Ltd., Contract No. 2690 (T.S.S. "ROSALIA"), we have to inform you that owing to a machining error on one shaft, making the diameter 208.5 m/m, at the Owners' request the other shaft was reduced to make both shafts alike before being sent to Messrs. Michell for assembly in the thrust blocks. The rule size for these shafts is 200 m/m.

We are, Dear Sir,

Yours faithfully,  
THE SURVEYORS,  
PER:

*J. St. Fraser.*

The Secretary,

LONDON.



© 2019

Lloyd's Register  
Foundation

W213-0120

Referred to the Chief Engineer

J.H.B.

19 MAR 1938

Noted  
Jus  
21.3.38

*[Faint handwritten text, possibly "Lloyd's Register"]*

*[Faint handwritten text]*

*[Faint handwritten text]*

*[Faint, mostly illegible typed text, possibly a letter or report]*



© 2019  
Lloyd's Register  
Foundation

*[Faint, mirrored text from the reverse side of the paper, including "Lloyd's Register" and "Foundation"]*