



Telephone No. : 286 Rugby.  
Telegrams : "Asteroidal, Rugby."

**THE BRITISH THOMSON-HOUSTON CO., LTD.,**

**Reqn. No. 574070/16**

(Please mention this number in all Correspondence,  
Invoices, Advice Notes, and on outside of each package).

**Messrs. Hadfields Ltd.,**

**East Hecla Works,**

**SHEFFIELD.**

**RUGBY.**

Date.....**15th May 1933.**.....

Please supply and deliver, subject to the conditions below, the following, Carriage Paid.

Delivery required at the destination given below by.....**19th June 1933 OR EARLIER.**.....

8 - Rough Turned Coupling Forgings Sk.945586.pt.1 MM.139 St.

4 - Rough Turned Coupling Sleeve Forgings Sk.945587.pt.1 MM.139 S.

TO BE INSPECTED AT WORKS OF SUPPLIER BY LLOYDS SURVEYOR.

ACCT. NO. 51  
MSO. 8-801123/4  
ROUTE 1  
SECTION D  
M.I. A. 5-5-33

Is Order must be acknowledged within 3 days.

DELIVERY TO :—WORKS STORES, RUGBY. (VIA LMS. RLY)

ADVICE NOTE LMM. 6-5-33 (AM)

duplicate to :—WORKS ORDER DEPT., RUGBY.

VOICES

duplicate to :—ACCOUNTING DEPT., RUGBY.

**The BRITISH THOMSON-HOUSTON Co., Ltd.**

Foundation

ORDER DEPT., RUGBY.

W214-0144