

2E

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

Serros Mark

Rpt.

Rot

No.

22491

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.This Survey, due *2-34* ~~partly~~ *was* held at~~now~~~~completed~~ and the following repairs carried out (due to *wear & tear*):—*Some Boiler tubes renewed**Alterations - New turbine motors to give increased power fitted.**Condenser lengthened & tubes renewed.*It is submitted the vessel is eligible to remain as classed, with notation of *TMC 10-33* as recommended.*Sg-33,**Amend NHP to 1000**21**13/1/33* 2019Lloyd's Register
Foundation*W214-0154**is eligible to remain as classed with fresh record of 7 Rm*