

TELEPHONE
5242-3



TELEGRAMS
THOMSONIAN, SUNDERLAND

ALL COMMUNICATIONS TO BE ADDRESSED TO THE COMPANY

JOSEPH L. THOMPSON & SONS LIMITED

SHIPBUILDERS
AND
REPAIRERS

ESTABLISHED 1846


*North Sands Shipbuilding Yard,
Sunderland.*

YOUR REF.

OUR REF. DO/MB.

29th. September, 1939.

Lloyds Surveyors,
55, Fawcett Street,
SUNDERLAND.



Dear Sirs,

No. 600 Ship.

Further to our letter of the 26th. inst.,
re scantlings of deep tank at the sides of the tunnel
in the after hold, our request that you should indicate
the extra scantling for tank not always full or empty
is intended for vegetable cargo oil, not oil fuel.

Yours faithfully,

FOR AND ON BEHALF OF
JOSEPH L. THOMPSON & SONS, LIMITED.

R. C. Thompson

Managing Director.

W. C. M.



© 2019

Lloyd's Register
Foundation

W216-0135