

STAR OF SUEZ
 THE 2ND S.S.No.1 BECAME DUE 2.42
 "EXAMINED 5.42" - 12 MONTHS

4-FEB1943

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "STAR OF SUEZ" REPORT N.Yk. No. 43121


For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Docking ~~When due~~

Subject to two tarpaulins being supplied and five hatch covers (charred) being dealt with at the first opportunity.

(Docking date)
 10.42.



© 2019

Lloyd's Register
 Foundation

W218-0160