

30 MAY 1928

GLASGOW REPORT No. 48013

(Received at London Office.....19....)

N. 101 Place Glasgow Date 1st June 1927

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to survey the installation of Doxford pumps in the Motor Vessel "Storsten"

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees of the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

That the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.



FOR BARCLAY, CURLE & Co., LTD.

John Shewan
ENGINE WORKS MANAGER

Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London. E.C.3.

Lloyd's Register Foundation

W219-0159

Please attach
to report



© 2019

Lloyd's Register
Foundation