

COPY.

Lloyd's Register of Shipping.



Port PHILADELPHIA, PA.

5th October, 1942

This is to Certify *that I have*

Surveyed the steel screw steamer "SUSANA", 5929 tons gross
register of Manila, P.I., on the 17th September, 1942, and
subsequently, while lying afloat at Girard Point, Phila., and
Port Richmond, Phila., on account of stated damage.

*and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have Recommended that she be* continued as classed,
without fresh record of survey, subject to rudder arms (EW)
indented shell plates B1 and 2, D1 and F1 (P.S.) and B2, D1 and
2 (S.S.) with structure in way being specially examined at

next drydocking. The vessel now

being fit to carry dry and perishable cargoes.

M. W. R. E. M. H. A. M.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."