

13 SEP 1940

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME....."SUSANA".....Rpt. H.Kg No. 8623

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs being effected to the foremast at the first opportunity. X

The HONG KONG Surveyors now report the vessel placed in dry dock, the bottom coated, repairs to shell and deck plating, wood deck etc., the foremast renewed and the mainmast part renewed.

The vessel has now been converted for oil burning in accordance with approved plans attached.

IT IS SUBMITTED the vessel appears worthy to remain as classed with record of survey 7.40. *without special conditions*

100A1
Shelter dk with freeboard } *without re.*
7.40 H.Kg
Fitted for oil fuel 7.40
X F.P. above 150° F (See Report 9) X



© 2019

Lloyd's Register
Foundation

W220-0007