

COPY.

# Lloyd's Register of Shipping.



Port

Hong Kong

1st, July 1940.

This is to Certify that I have

Surveyed the ~~Boiler~~ and ~~Machinery of the~~ Propeller, Propeller  
Shaft and Fitting of Oil Burning Installation of the S.S.  
"SUSANA" of Manila, P.I., 5929 Gross Tons, No. 34410 in the  
Register Book.

and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all  
recommendations made by me in connection therewith have  
been carried out to my satisfaction, and that I have  
Recommended that the record of ~~Tail Shaft seen C.L. 6-40.~~

be made in the Register Book in the case of this vessel.


P.T.O.

*Chas R Rowcliffe*

Engineer Surbeyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."





Wood deck on poop renewed.

Other minor repairs effected.

COPY.

## Lloyd's Register of Shipping.

All pipes and fittings for the burning of oil fuel  
flash point above 150°F. now installed on board & tested.  
One shell plate Port side forward fitted with doubling plate.  
One deck plate abreast main mast Starboard side renewed.

Fore mast renewed except cross-tree.

Main mast part renewed.

Four sampson posts repaired.

Four side lights (new permanently closed) electric  
welded all round.

Surveyed the vessel and found her to be in good condition.

Other minor repairs effected.

"SUSANA" of Manila, 7.1. 1929 Gross Tonnage, No. 36410 in the

Register Book.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of this vessel be 6-40.


be made in the Register Book in the case of this vessel.

Y.F.O.

*John R. Kew*

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
"While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register  
Foundation