

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor 25-342

VESSEL'S NAME T I E N K W A N G

Rpt. Sng.

No. 6975

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

(The 2nd S.S. No. 1 became due 3.41).

A Notation of 'Examined 3.41' valid for 12 months has been assigned.

The SINGAPORE Surveyor reports (8.41) the vessel placed in dry dock, bottom coated and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of docking survey 8.41.

As now.

8,41 Sng.

now a war loss



6/11/20
© 2020
18.3.42

Lloyd's Register
Foundation

W222-0172