

# Lloyd's Register of Shipping.

(Reconnu par la Loi Belge sur la sécurité des Navires.)  
(Arrêté Ministériel du 8 Janvier, 1921.)

Mersey House,

Quai de Rouen, 1,

Antwerp, 21st December 1935.

23 DEC 1935

ARRD. 23  
LONDON

Dear Sir,

I have to confirm and acknowledge the following  
We have to confirm the following cablegrams passed  
between us yesterday:-

RECEIVED

"VEERHAVEN REFERRING SKETCH FORWARDED SHOWING CRACKS  
ON UNDER SURFACE PIECE CUT FROM BUTTSTRAP FROM  
INFORMATION RECEIVED ROTTERDAM SURVEYORS THESE CRACKS  
ARE IN SHELL PLATING CABLE YOUR REMARKS."

RECEIVED

"STEAMER VEERHAVEN YOUR TELEGRAM RECEIVED SKETCH CORRECT  
CRACKS ARE IN UNDERSURFACE PIECE CUT FROM BUTTSTRAP  
NOT IN SHELL PLATING HAVE PERSONALLY EXAMINED THESE  
PARTS".

We are, Dear Sir,

Yours faithfully,

The Surveyors,

per. - *W. J. H. K. K. K.*

The Secretary,

ROTTERDAM.

The Secretary,

LONDON.



© 2019

Lloyd's Register  
Foundation

W226-0167

W226-0168



PAID-355w

LONDON.

SECRETARY.

*[Handwritten signature]*

23 DEC 1935

Referred to the Chief Engineer Surveyor

Referred to Mr. *[Handwritten name]*

*[Handwritten signature]*

Bel. -

The Submarine

London Electric

We are, Dear Sir,

"STEWART AND CUNNINGHAM LTD LONDON RECEIVED SKETCH CONCERNING  
NOT IN SHEET PLATING HAVE PERSONALLY EXAMINED THESE  
CRACKS ARE IN UNDER-SURFACE PLATE CUT SHOWN BOLTS ARE  
STEAMER VESSEL HAVE YOU LONDON RECEIVED SKETCH CONCERNING

THE IN SHEET PLATING GIVE YOUR REMARKS.  
INFORMATION RECEIVED BOLTS AND SUBMARINE THESE CRACKS  
ON UNDER SURFACE PLATE CUT SHOWN BOLTS ARE SHOWN  
"STEWART AND CUNNINGHAM LTD LONDON RECEIVED SKETCH CONCERNING CRACKS

DEVI

seen in vessel:-

we have to confirm the following cablegrams received

LONDON

23 DEC 1935

Answer, please, 1332.

Quai de Rouen, 1,  
Messager House,

(Address: Ministry of War, 8, rue de la Paix, 1011.)  
(Received by the Ministry of War, 1011.)

Ministry of War

Floyd's Register Foundation