

**COPY.**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

Dear Sir,

The Dutch Steamer "VEERHAVEN" No. 2322 in the Register Book is having a tween deck fitted in No. 1 Hold. The work is now in process of erection and a mistake has been made in the thickness of the Hatchway side coverings these being 12 thick instead of 10 as approved.

REGISTER  
ANTWERP

A sketch of the compensating structure is forwarded herewith for your consideration. The structure is a wooden frame with a height of 8 feet 6 inches. The width of the structure is 12 feet 6 inches. The structure is to be fitted in the No. 1 Hold. The structure is to be fitted in the No. 1 Hold. The structure is to be fitted in the No. 1 Hold.

The matter is rather a local one and the registers will appreciate early approval, by which, if possible.

It is now pointed out on the plan that the height of the tween deck has been reduced from nine feet to eight feet.

The plan approved by the Holland Carriers is also forwarded, which please return.

Yours faithfully,



© 2020

Lloyd's Register  
Foundation

W226-0198