

Medical surveys, when held, must be reported in detail and seriatim in the case of Repairs, if any, and, in detail, the nature and extent of Examinations amount of Damage (the cause of which must be stated) should be separated from details being detailed in the body of the report, should be briefly summarised at the end of the report.

[Thin Copy for attaching to Report.]

Lloyd's Register of Shipping.

Port of PIRAEUS,

21st February, 1941.

Dear Sirs,

With reference to the survey now being held on the Steamer "ARTEMIS PITTA"

I beg to inform you that, ~~in consequence of~~ the condition of this vessel's

it will be my duty to recommend to the Committee that the ~~same be~~ two stoppered plain tubes in the port boiler be renewed before the end of May 1941

as provided for in the Rules, extracts from which appear on the other side:—the continuance of the vessel's character in the Society's Register Book to be subject to the due fulfilment of this condition.

I am,

Yours faithfully,

D. A. Parissis
Engineer Surveyor to Lloyd's Register.

To Messrs. G. N. Pittas Bros. & Co.,

PIRAEUS.



Lloyd's Register Foundation