

COPY.

Lloyd's Register of Shipping.



Port

NEW YORK

MARCH 7, 1940

This is to Certify that I have

Surveyed the **M.V. "BRAGANZA" 6327 tons gross register of Oslo**
on account of **dry docking and repairs**

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have **Recommended** that she be **continued as classed** with fresh record of survey 2-40, subject to permanent repairs on cracked shell plate (SSP) being effected at Owners' convenience

being fit to carry **dry and perishable cargoes.**

(signed) W. Boylan

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”