

"Dumra."

Gls. 42119.

It is submitted that the Glasgow Surveyor should be requested to state where the donkey boiler is fixed. Number, description & area of the safety valves, the pressure to which they were adjusted & if fitted with casing gear.

J.W.D.

5/10/22

Lloyd's Register
Foundation

W 239 - 0020