

Main Boilers

Donkey Boilers

Owners British India Steam Nav Co Ltd Port

M. V. "DUMRA"

{ Gls. No. 42119
{ Gls. No. 42085

re dealing with this case, the Glasgow Surveyors
be asked to forward a list of Spare gear supplied,
is not mentioned on the report.

C. H. D.

4/9/22

Lloyd's Register
Foundation
W239-0023

To what pressure were they afterwards adj

To what pressure were they afterwards adj