

71

0

Moulded

16

0

Top of Floors to top of main Deck Beams

7

10

No. of Tiers of Bes

7.85

Moulded Depth 8 #

ins Round of

Chief Surveyors 23.9.08

Received from Chief Surveyors

EL'S NAME Lt. S.S. Lug No. 206

Report G.

No. 27009

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Name of Survey

First entry

When due

± 100 A 1 ("Steel") "For Towing purpose."

18R (ft Stl - ft Wood)

BK 5" 4BH Conn. Lloyd's A&CP

C. H. J. 23/9/08

© 2019



Lloyd's Register Foundation

W24 - 0047

Deck Material and thickness

Hold Stringer Plate