

Report to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "E.G. SEUBERT" Report Phl. No. 8406

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey..... Docking ~~Under~~

Subject to permanent repairs to indented bottom plating etc. at the first convenient opportunity.

Handwritten initials and date: *has*
18.10.43

© 2020

Lloyd's Register Foundation

W240-0213