

1m.9.37.

fees paid

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M.V. "DORYSSA"

Rpt.

Nwc. No. 96601

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

1st Long. No.	15640	Depth "d"	-
2nd Long. No.	42780	Proportions = $\frac{L}{D}$	13.52
Framing	As approved	Sheerstrake	As approved

This is a sister ship to the "DAPHNELLA"

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

100AL "Carrying petroleum in bulk"

1 Dk., 2nd Dk. clear of cargo tanks, "Longitudinal framing at bottom and at deck"

Cell.DBu^E 64' 160t, DTf 25' 271t, FPT 138t, APT 86t.

FK, 17BH, Lloyd's A & CP.

P 91', B 43', F 69'.

Machy. aft

O.L. 483.3'.

30.8.38
J. Paul



© 2019

Lloyd's Register Foundation

W241-0150