

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME

"HAYBURN WYKE"

Report Hul.

No. 50692

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/92.)

No. 1 SURVEY PARTLY HELD. 3.40-not advanced.

due 7.38

When proposed to be completed -

to be

tion of Survey held, &c.: - sea connections, condenser, auxiliary pumps and pumping arrangements require to be examined and the steam pipes tested.


The year of grace expired 7,39.

The vessel has been requisitioned by the Admiralty.

Noted.

© 2019

Lloyd's Register
Foundation



W246-0594