

Size of compensating ring 33 x 4 x 1/2 No. and Description of Furnaces in each boiler 3: Delightous Material Steel  
Length of valve seat top } Thickness of plates crown } 19/32 Description of longitudinal joint Weld No. of strength

Lake Hall will

Lon. 109644

A new 12 H.P. Steam driven generator now fitted  
in addition to existing Set. (May. 1941)



Y Run  
© 2019  
9.7.41

Lloyd's Register  
Foundation

W246-0188.6

Working pressure of end plates

Area of safety valves to superheater

Are they fitted with easing gear