

REPORT OF SURVEY FOR REPAIRS, &c.

of writing Report... 19... When handed in at Local Office... 19... Port of Gibraltar
 o. in Survey held at... Date, First Survey... Last Survey... 12 19 43
 Book...
249 on the Wood, Iron or Steel ss "Ingman" (No. of Visits...)
 TONNAGE:— Built at Port Glasgow By whom A. Rodger & Co. When 1907 10
 ROSS 3169 Owners MOWY Owners' Address...
 UNDER DK 2991 Managers Harper, Matthew & Co. Ltd Port belonging to London
1997

Afloat or in Dry Dock? Name of Dock... Destined Voyage...
 DBa... feet; uE & B... feet; f... feet
 city... tons. FPT... tons; APT... tons; MT... feet... tons.

All alterations in the existing records should be underlined.

Report, No. 54841 Port GPP

veys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete
 s should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations
 uent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to
 s; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
 t of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.
 he dates and initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he
 d his services for this purpose and to whom and why they were declined.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)	
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
<u>+100 A1 spar</u>	<u>+LMC 5.41</u>
<u>dk with freeboard</u>	<u>BS 4.43</u>
<u>11.43</u>	<u>TS CL 4.42</u>
<u>ss 1st 2 No 3-10.32</u>	<u>NDB 24</u>
<u>ss 1st No 1-37</u>	<u>Examined 4.42</u>
<u>Cargo battens not fitted.</u>	
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.	

Was a damage report made by anyone else? if so, by whom?

Donkey boiler not to be used.

OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
... ..								
and Faired or Repaired								
or Repaired in place								

DITION OF THE

Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year.
Cement or Asphalt	Oil Bunkers	Boats
Rudder	Scuppers	Masts, Yards, &c.
Steering gear and its connections	Cargo Hatchways	Condition, how ascertained. (State if wedges removed.)
Windlass	Hatches	Equipment letter
Have pumps been examined and found efficient?	Planking	Anchors, No. of
Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged).
Have Watertight Doors been examined and found efficient?	Treenails	length mean diamr. (on board.)
Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
	" " at other places	Standing and Running Rigging
	Stringers, Clamps & Shelves	Sails
	Salting (State if examined.)	

Observations, Opinion as to Class, Recommendation, &c.:—

ate clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
 ay, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
 38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Section 29	£	:	:	Fees applied for,
or Repair Fee (if any)	£	:	:	19.
ses (if chargeable)	£	:	:	Received by me,
	£	:	:	19.
Surveyor's Fee (if any)	£	:	:	

nittee's Minute


acter Assigned

Sub. Kull 17/2

TUE. 29 FEB 1944

Deferred for Cont. G.E.

Surveyor to Lloyd's Register of Shipping.



© 2019

Lloyd's Register Foundation

W246-0188

Is Certificate required? If so, to be sent to