

TELEGRAMS:
'CORRUGATED'
MOTHERWELL."

SPECIALTY: CORRUGATED FURNACES.

TELEPHONE:
MOTHERWELL 176

THE BROOMSIDE BOILER WORKS COY LTD
CAMP ROAD,
MOTHERWELL,
LANARKSHIRE.

S. J. Kimpwood,

30th July 1937.

New rep. No. 95-796.

To Messrs The North Eastern Marine Engineering Co. Ltd.,
WALLSEND-on-TYNE.

Order No. B.3/23. Ex The Boiler
Furnace Co. Ltd.

Our Job No. 934

Engine No. 2901 (Aux).


2 "Deighton" section CORRUGATED FURNACES,
with Stephen Gourlay back ends.

Length: 7 ft 0.3/4".
Int. diam. 3 ft 4.1/16"
Thickness: 19/32"

Plates by Colvilles Ltd.

Nos. 1008, 1008.

The Plates have been subjected to mechanical tests and the Furnaces passed
for workmanship and found satisfactory by the Surveyor.



Lloyd's Register
Foundation

W249-0060