

COPY.

Lloyd's Register of Shipping.

Collingwood Buildings,

Newcastle-on-Tyne.

7th October, 1937.

Dear Sir,

S.S. "KINGSWOOD".

With reference to your letter dated the 2nd October, 1937, addressed to the Secretary of this Society by Mr. J. P. Hurworth, requesting information of repairs carried out on the Auxiliary Boiler since its installation in the vessel, and prior to ^{the} explosion from the Boiler on the 3rd January, 1937, we have to inform you that the reports of surveys carried out on this Boiler have been examined, and it would appear that the only repairs carried out were the renewal of the plain tubes, reported by the Swansea Surveyors early in January, 1934, when the Boiler was tested by hydraulic pressure to 205 lbs. per square inch.

We are, Dear Sir,

Yours faithfully,

THE SURVEYORS,
per *M.G.*

The Principal Officer,
Board of Trade Surveyors' Office,
NEWCASTLE ON TYNE.



© 2020

Lloyd's Register

Foundation
W249-01140