


ALL CORRESPONDENCE SHOULD BE ADDRESSED TO THE FIRM AND NOT TO INDIVIDUALS

CONSTANTINE LINE

CONSTANTINE STEAMSHIP LINE LTD.
CONSTANTINE SHIPPING CO. LTD.



LONDON OFFICE,
H. CONSTANTINE & SONS, (LONDON) LTD.,
BALTIMORE EXCHANGE CHAMBERS,
24, ST. MARY AXE,
LONDON, E.C. 3.

CANADIAN OFFICE,
H. CONSTANTINE STEAMSHIP LINE LTD.,
69, BOARD OF TRADE BUILDING,
MONTREAL, P.Q.


TELEGRAMS:
CONSTANT MIDDLESBROUGH
TELEPHONE 3445

MARITIME BUILDINGS,
Claims "A" Department MIDDLESBROUGH.

C/5.

22nd January, 1937

Mr. Ritchie, Esq.,
Lloyd's Register of Shipping,
LONDON E.C. 3.



Dear Mr Ritchie,


s.s. "KINGSWOOD".

I confirm telephone conversation of today when
I gave you in confidence the contents of a cable
which we had received from the Master of this vessel,
which reads as follows : -

COMMONWEALTH GOVERNMENT ENGINEER COMPLETED INVESTIGATIONS
TODAY REPORTS CANNOT FIND CAUSE EXPLOSION NO DEFECTS DONKEY
BOILER".

You will appreciate that this information at the
moment is confidential, and no doubt we shall be getting
confirmation of this through official sources.

Yours sincerely,



© 2020

Lloyd's Register
Foundation

SVB

23 JAN 1937

Mr. Raden

1880

22

© 2020
Floyd's Register
Foundation