

1m.10.40.

1

4 JUN 1941

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME DERRYMORE Report GAL No. 4050

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING When due.....

Noted  
was  
3-6-41

Delete from S.R.L.



© 2019

Lloyd's Register  
Foundation

W25-0011

Longitudinals	Have Stowage valves been examined and found efficient?	Treenails	Cables (State length)
Transverses		Breasthooks & Stemson	
Floors	Have Watertight Doors been examined and found		

Per ipst Good