

COPY.

# Lloyd's Register of Shipping.

10 NOV 1944



All alterations in the existing records should be underlined.

Port, No. 6248 Port *W/Ch*

Port

BELFAST

3rd November 1944

## This is to Certify that I have

Surveyed the S.S. "MOUNT OREBYNS", 6527 tons gross, of Greece, for Hull repairs, whilst lying afloat at Collock Dock, Belfast, on the 26th October 1944 and subsequently

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and

that I have **Recommended** that she be retained as classed without fresh record of survey. The vessel's class is subject to permanent repairs to D.E. drain well (p.s.) at first opp. to shelter deck plating between hatchways being dealt with at next Gen. Exam. To indented shell plates in No. 3 in sheerstrake (p.s.) 1st and 2nd below (a.s.) and 5th below (p.s.) and to stiffeners to fore end of Nos. 1 and 4 hatchways being repaired at first opportunity. Also to a bower anchor and 30 fathoms cable being being fit to carry end of the present emergency. All as previously recommended.

being fit to carry any and perishable cargoes.

*Edwin Griener.*

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:— While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Surveyors or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register Foundation W252-0029