

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also

SPECIAL NOTE.

Notation of No. 3-4.33 to be amended to 2nd No. 3
when plating drilled.



© 2020

Lloyd's Register
Foundation

W256-0133

The rudder has been removed for testing the alignment,
the rudder pintles and gudgeons dealt with, deck plating