

30 AUG 1944

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "RADBURY" REPORT P.N.L. No. 4286

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 3rd S.S. No.2 due 7.42.

Notation of "Examined 2.44" valid for 12 months was assigned.

The class is subject to indented plating in G & H strakes (p & s) being dealt with at the Owners' convenience.

The PORT NATAL Surveyor reports (6.44) this vessel afloat and due to wear and tear (holed) shell plate 2nd from forward in 8th strake below sheer (s.s.) renewed.

IT IS SUBMITTED the vessel is worthy to remain as classed subject as above.

As now, subject.

*B.A.M.* J.F.  
29.8.44



© 2019

Lloyd's Register  
Foundation

W258-0191