

Chief Ship Surveyor 25. 2. 19

Received from Chief Ship Surveyor

NAME Steel S.S. "ROYAL STAR". Rpt. Bry. No. 17081

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

It is submitted the Belfast Surveyors be requested to state whether they are correct in reporting that the rivets in the butts of "A", "B", "C" & "D" strakes are spaced 4" apart from centre to centre.

M
25. 2. 19

N
W. 25/2/19



© 2020

Lloyd's Register Foundation

W259-0014

MS, Forecastle Deck, Angle, Bulb Angle,	8	3	50	8	3	50		
Plato, Tee Bulb or Channel								
Angles on upper edge								
Angle on ditto								