

STANLEY & JOHN THOMPSON, LTD.,
LONDON.

COPY

THE WALLSEND SLIPWAY & ENG. CO.LTD.

WALLSEND ON TYNE.

18th February 1938.

Messrs. J.L. Thompson & Sons Ltd.,
SUNDERLAND.

Dear Sirs,

SHIP NO. 588 - CONTRACT NO. 932.

We are in receipt of your letter of the 17th instant and the enclosed copies of letters from Lloyds Register to the Owners and to their representative in Dusseldorf relating to the defect in one of the boiler drums being manufactured for the above vessel, and note that the Owners approve of machining the interior of the drum such that the thickness of the drum wall shall not be less than 2".

With regard to this matter we have arranged to machine the interior 4' - 2. 5/16" diameter the whole length of the drum and maintaining throughout the original thickness.

Yours faithfully,



© 2019

Lloyd's Register
Foundation

W261-0179