

LLOYDS' SURVEYORS' ADVICE NOTE FOR BOILER MATERIAL.

TELEPHONES: (FREE TRUNKS FROM GLASGOW. TO HEAD OFFICE, MOTHERWELL. ALSO LOCAL TELEPHONE CALL AND PRIVATE WIRE FROM GLASGOW OFFICE TO HEAD OFFICE, MOTHERWELL.)
POST OFFICE 5 CENTRAL. NATIONAL 7155 CITY. MOTHERWELL NO 9.

St. Donna. No. 11. 29/1/38
D. Steel & Iron Works.

Motherwell, 14/8/15
Messrs. Chas. A. Holmes & Co. Ltd. Mull.

191

Bought of DAVID COLVILLE & SONS. (LIMITED.)

STEEL by OPEN HEARTH PROCESS.

BOILER STEEL BRANDED  SHIP STEEL BRANDED 

Iron Branded "DALZELL" with the Distinguishing Quality

ALL STEEL TESTED BEFORE LEAVING THE WORKS. - IRON WHEN REQUIRED OF A SPECIFIED STRENGTH & DUCTILITY ALSO TESTED BEFORE BEING DESPATCHED.

ON ADMIRALTY AND WAR OFFICE LISTS
CONTRACTORS TO
BRITISH COLONIAL AND FOREIGN GOVERNMENTS

Brand



Batch No. in

1343. 34 = 20. 4 = 5. 40 = 2. 34 = 6.

To Bbr. Dehl. Kingston St. Str. Mull 16 R

Date & No of Order	Marks	No of	Length	Breadth	Thick	Tons	Cwts	Qrs	Lbs	Numbers stamped on Material
15/3/15	1114			Boiler Plates						
4229	6	2	5-1	60	4/8	16	1	4		24271 y.
30	8	2	4-11	60	33/32	1	1	34		23589 y.
	9	1	9-6 1/2	50			10	2 1/2		3094 y.
	10	2	14-10	38	11/16	1	4	- 16		3368 y.
	11	1	18-1	"	"		14	2 1/2		3499 y.
	12	2	6-4	"	"		9	3 1/4		4003 y.
	14	2	9-1 1/2	18 1/2	1 1/32		10	2 1/2		2948 y.
	16	16	3-4 1/2	15 1/2	7/8	1	3	2 8		16381 w.
	14	4	"	16 1/2	"		6	1 -		4381 w.
	18	1	4-11	38	3/4		4	1 19		3999 y.
		33					4	2 1 2		

Copy Original signed 25-8-1915

TENSILE STRENGTH W. = 98 TO 99 TONS

Y. = 96 to 98 tons.

© 2020
awfont
SURVEYOR LLOYDS' REGISTER
Lloyd's Register
Oct. 29th 1915
Foundation

W271-0203